

OUR PROJECT IS TO RESTORE VOLIR BUILDING

Current works Update -

Block 24 (1-13) Unit 11 Penthouse -

VBS have-

- Completed Sheet Membrane installation and testing.
- Removal of redundant building materials.
- Completed the detailing of all outlets on rooftop deck.
- Preperation of tile beds for the tilers
- Preperation of door units on balcony







VBS Watt Street Remedial Works Update

15th February 2016

IN THIS ISSUE



Completion of Sheet Membrane installation Rooftop area of Building 24 & Testing is now complete -

VBS have completed the Installation of the Sika Sarnafil sheet membrane and installed the correct detailing to outlets etc.

We have conducted rigorous Water testing to confirm watertight seal before the installation of bedding and new tiles. This involves FLOOD TESTING the newly repaired areas over lengthy periods to determine all areas are water tight.

VBS are installing SIKA SARNAFIL 2mm system to all roof top areas which is above and beyond the Scoped requirements.


Block 26 (12-50) Balconies over the Commercial Units -

VBS have-

- We are in the final stages of tiling exterior decks over the commercial units.
- All remedial works on the door units are nearing completion including internal finishes.
- Painting has commenced along external front façade.











VBS CAN KEEP YOU UPDATED -**EMAIL YOU NAME** UNIT#

AND CONTACT DETAILS TO RECEIVE THIS NEWSLETTER TO

KAREN@VICTORBUILDING.COM.AU

Block 26 (12-50) Roof top terrace area U46, 44, 43, 42 & 41-

VBS have-

- All of the top decks have had the planter box walls removed and preperation is under way for the installation of sheet membrane.
- Unit 41 is first to have sheet membrane installed.
- Unit 42 install leak control flanges.









